

**From:** [Wallingford, Jonni B.](#)  
**To:** [Sheldrake, Sean](#); [Zhen, Davis](#); [Young, Hunter](#)  
**Cc:** [younghs@cdmsmith.com](mailto:younghs@cdmsmith.com); [Scott Coffey](#); [Vickstrom, Kyle E.](#)  
**Subject:** Sediment Trap Oversight  
**Date:** Wednesday, January 30, 2019 10:54:05 AM  
**Attachments:** [IMG\\_20190130\\_104822383\\_HDR.jpg](#)  
[IMG\\_20190130\\_104844902\\_HDR.jpg](#)

---

Hello,

The Pre-RD has retrieved ST06A (RM 11.8 east bank) and is preparing to lower the replacement traps to the diver for installation.

Sediment traps appear to have vegetation and shrimp in the tubes.

Jonni

(b) (6)

ST06A



Lowering new traps into water



Get [Outlook for Android](#)